


MA 27-F

Giunzione intermedia passaparete, femmina

Bulkhead union, female

Union traversée de cloison, femelle

Gerade Schottverschraubung
weiblich

Type	Ø Tubo	D1	D2	L1	L2	L3	CH1	CH2	g Δ
new 27 06 18 -F	6	G1/8	M14x1	7	26,5	9	18	18	-
new 27 06 14 -F	6	G1/4	M14x1	10	30,5	9	18	18	-
new 27 08 18 -F	8	G1/8	M16x1	7	26,5	9	20	20	-
new 27 08 14 -F	8	G1/4	M16x1	10	30,5	9	20	20	-
new 27 10 38 -F	10	G3/8	M18x1	11	33	10	22	22	-


MA 28

Gomito intermedio

Union elbow

Raccord à coude

Winkelverschraubung



Type	Ø Tubo	D2	L1	g Δ
28 03 03	3	7	12,8	4,5
28 04 04	4	9	17,5	9
28 06 06	6	12	20,5	16,5
28 08 08	8	14	22,5	22
28 10 10	10	16	25	29,5
28 12 12	12	19	26,5	48,5
28 14 14	14	22	31,5	58
28 16 16	16	24	36,5	90,6


MA 29

T intermedio

Union tee

T égal

T-Verschraubung



Type	Ø Tubo1	Ø Tubo2	D1	D2	L1	L2	g Δ
29 03 03	3	3	7	7	12,8	25,6	5,6
29 04 04	4	4	9	9	17,5	35	12,5
29 06 06	6	6	12	12	20	40	22,5
new 29 06 04	6	4	12	9	18	40	-
29 08 08	8	8	14	14	21	42	28
new 29 08 06	8	6	14	12	20,5	42	-
29 10 10	10	10	16	16	24,5	49	39,2
new 29 10 08	10	8	16	14	23	49	-
29 12 12	12	12	19	19	26	52	61,3
new 29 12 10	12	10	19	16	26	52	-
29 14 14	14	14	22	22	30,5	61	77,1
29 16 16	16	16	24	24	34,5	69	124


MA 31

Asta singola

Simple screw

Vis simple

Hohlschraube



Type	D1	L1	L2	L3	CH	g Δ
31 00 M5	M5x0,8	4,1	14,3	18,5	8	2,5
31 00 18	G1/8	4,4	21,2	27	14	13,4
31 00 14	G1/4	5,9	24,7	31,5	17	27,8
31 00 38	G3/8	6,4	28,2	36	20	43
31 00 12	G1/2	7,5	33,5	41,5	26	80,5